


ARE YOUR LUG NUTS A **HIDDEN PROBLEM?**



SWOLLEN



MISSING CAP

Many original-equipment lug nuts come with aluminum caps that can wear out, swell, and even break off, making them impossible to remove and leaving you stranded on the roadside.

**WE CAN SOLVE THE PROBLEM BY REPLACING
YOUR LUG NUTS TO KEEP YOU SAFE!**

Our lug nuts are designed to perfectly fit your original-equipment wheels.



Hanco Corporation
Eagan, MN 55121
www.hancousa.com
800.328.7400

ASCOTTM
Supply Corporation